


Fisher & Paykel Electric Ceramic Glass Cooktops Models CE604CB, CE604LB & CE905CB



Manufactured between 1 June 2011 and 11 November 2015 and sold nationally from 1 June 2011

IDENTIFICATION: Affected model numbers start with CE604CB, CE604LB or CE905CB and serial numbers start with 1, 2, 3, 4, BK, BL, BU, BY, EF, EI and ES.

DEFECT: Accessible parts may not be effectively earthed.

HAZARD: Spills around the control panel and dials can leak into the electrical components. This may cause an electric shock to the user that can result in severe injury or electrocution.

ACTION REQUIRED: Check the model and serial number on the back of your cooktop's User Guide as shown below to determine whether your cooktop is recalled.



If your cooktop is recalled, contact Fisher & Paykel to book a free repair at 1300 023 350, (Mon-Fri 6am-7pm AEDT, Sat 7am-2pm AEDT) or via <u>www.fisherpaykel.com.au</u>. If you are in doubt or if you don't have a User Guide, contact Fisher & Paykel to confirm whether your cooktop is recalled and to book a free repair for recalled cooktops.

If your cooktop is recalled and a spill on your cooktop has reached the control panel or dials, immediately turn off the power supply to the cooktop and do not use it until repaired.

See <u>www.productsafety.gov.au</u> for Australian product recall information